ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0365, W0363, W0302, W0254, W0441	Chikka Muniswammappa Lyt, 2nd Crs, R H B Colcny 1st Main Rd, Vidya Nursary School & Raj Colony Rd, N	Gatepalya 1st cross and 2nd cross
Segment No.	**Total Length (m)**	
12/C-W0365/S024645	218.70	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.14	77.518185	13.067635	77.517917	13.067029	W0365	W0365
2	145.56	77.516546	13.068601	77.516819	13.067313	W0441	W0441

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements road and drains in 1st to 3rd cross road Gatepalya in ward no.12 Shettyhalli Sub Division	5500000	2020
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		012-20-000040
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/595/2019-20	28/03/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
18/12/2020	18/12/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s KRIDL		5482170.00
Phone No.	**E-Mail ID**	
7760876222		

Field Inspection Details

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0365, W0363, W0302, W0254, W0441

Name

gatepalyaroad

Number of Trees

4

Any Other Information

gatepalya

Date of Inspection

12/02/2021

Remarks

cc road in 1st cross & 2nd cross

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		Location was not determined.
Footpath Condition		This photo seems out of range.
Footpath Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		Location was not determined.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli

Street ID: W0365, W0363, W0302, W0254,

Segment Start

Location was not determined

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	05/03/2021	14/03/2021	Approved
EE	EE DAS	26/02/2021	14/03/2021	COMPLETED
AEE	M Nageshmurthy	26/02/2021	14/03/2021	remarks
AE	A.P. Shivakumar	26/02/2021	14/03/2021	approved
AE	A.P. Shivakumar	12/02/2021	14/03/2021	approved